

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model HC-CZYK-1BF

High/Feather _____

Propeller S/N CH37275B

Start Lock _____

Propeller Design F7666A

Low _____

Blade S/N's

Reverse _____

1 J 91883

2 J 91885

Aircraft Manufacturer Aviat Aircraft Inc.

3 _____

Aircraft Model A-1B

4 _____

S/N 2247

5 _____

Registration N727HY

6 _____

Manufacturer Assembly Part No. 836-60

te	Propeller		A/C	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO	Hrs	
03	0.0	0.0	0.0	Installed New Hartzell HC-C2YK-1BF/F7666A Propeller on New Aviat Aircraft Inc model A-1B S/N 2247.
03	2.8	0.0	2.8	Flight Test Time. Alumit Humbert for Aviat Aircraft Inc.
04	69.1		69.1	I certify that this prop has been inspected i/d/w on annual/100hr inspection and is airworthy. A J Fuchs AIP 292905771 IA
05	94.9		94.9	AD's checked through 2005-24. I certify that this prop has been inspected i/d/w on annual inspection and is determined to be in airworthy condition. A Woodruff AP553697406 IA

				NOTE 01-01-07 TACH 152.4 TOTRE 152.4
				I CERTIFY THAT THIS AIRCRAFT, ENGINE
				PROP HAS BEEN INSPECTED IN ACCORDANCE
				WITH AN ANNUAL INSPECTION AND WAS DETER-
				MINED TO BE IN AIRWORTHY CONDITION
				<i>[Signature]</i> AIP 2747316 IA