

PROPELLER LOC

PROPELLER MODEL PHC-534F-1RF/F76

PROPELLER S/N FP1788B

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

IR-22 CUTTER AVIATION DEER VALLEY INC. TACH 573.3
1262 530 WEST DEER VALLEY ROAD Total Time 573.3
J11W PHOENIX ARIZONA 85027

HC-J3YF1RF
P1788B

100 hr/Annual Inspection and lubrication as per Cutter Aviation checklist. Dressed and
propeller blades. AD's checked through bi-weekly dated 06/05/2003.
propeller has been inspected in accordance with a 100 hr/Annual inspection and was found
OK at this time.

6/23/03 SIGNATURE [Signature] W45R0450

Details of work accomplished on this aircraft are on file at this agency under work order #M0074

*****END*****



