

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-334F-1RF

PROPELLER S/N FP5148B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position ONE

PITCH RANGE

Propeller Model PHC-53F-1RF

High/Feather _____

Propeller S/N FP5148B

Start Lock _____

Blade Design F1392-1

Low _____

Blade S/N's

Reverse _____

No. 1 K44515

Aircraft Manufacturer Cessna

No. 2 K44519

Aircraft Model SR20

No. 3 K44512

S/N 1744

No. 4 _____

Registration N258CP

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		

MODEL: SR20
S/N: 1744
REG. No. N258CP

CORPORATE FLIGHT MANAGEMENT, INC.
625 FITZHUGH BLVD.
SMYRNA, TN 37167 (615) 459-8883

DATE: 10/5/2007
Hobbs: 104.6
Flight 76.0
Hobbs:

Propeller S/N FP5148B

Inspection:

Complied with annual inspection per Cirrus SR20 AMM 5-20.

Airworthiness Directives:

AD 2005-14-11, N/A, no record of work performed by Southern California Propeller Service.

Maintenance Accomplished:

The propeller identified above was inspected in accordance with a annual inspection as required by FAR 91.409(F) (3) and is approved for return to service. Details of the repair and inspection are on file at this Repair Station under Work Order N°. 15936 Dated 10/5/07.

Signed: *[Signature]*

For: **Corporate Flight Management, Inc.**

Certified Repair Station

FJTR920D

SPECTRUM
AVIATION

4029 Airport Road, Suite 300 Lexington, KY 40510 859-255-1902

Propeller Log Book

Date: 11/21/08
Reg No: 258CP
Flight Time: 96.0

Aircraft: Cirrus SR20
Hobbs: 130.7

Serial No: 1744


Complied with annual inspection I/A/W Cirrus Maintenance Manual and Hartzell maintenance practices.

1. Lubed propeller with Aeroshell 6.
2. Cleaned propeller.
3. Checked and found all AD's are current.

The aircraft, airframe, engine, propeller, or appliance identified was repaired and/or inspected in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service for the work performed.

Date: 11/21/08

Signed


CA3266201